

Contact

Andreas Eisenmann
 Product Engineer
 Mobile: 267-980-5569
 Eisenmann.Andreas@us.sika.com

SikaBond & DriTac with Advantech Subflooring Testing

August 19th, 2021

To whom it may concern,

Regarding the testing of the below list of membranes, Sika Corporation has the following comments:

Product	Application	Pass/Fail	Comments
AdvanTech X-Factor	SikaBond-T21 SikaBond-T100 DriTac 7700 DriTac 7800 DriTac 7300 DriTac 4141 DriTac 5900	PASS	5900- Must give proper time flash.
EXACOR Magnesium-Oxide	SikaBond-T21 SikaBond-T100 DriTac 7700 DriTac 7300 DriTac 4141 DriTac 5900	PASS	
Advantech Mag Oxide	DriTac 7800	FAIL	
Pull Tests at °70F / 50% R.H. after 7 days			

Please be advised that this in-house testing depicts results independent of time and weather-related effects. These results should only be used as a guide. Actual test results in the field may vary over an extended period under field conditions.

Sika’s warranty is subject to full compliance with Sika’s instruction for use, handling, storage, and warnings applicable to the Sika products as set forth on Sika’s Product Data Sheet’s, labels any written recommendations issued by Sika. Failure to comply will result in no warranty being issued or will render existing warranty void.

Should additional information be required, please contact the local Sika representatives, consult the Product Data Sheet located on the website at usa.sika.com, or reach out to Sika’s Technical Service Department at 1-800-933-SIKA.

Sincerely,



Andreas Eisenmann
 Product Engineer –Floor Covering Installation
 Building Finishes TM

SIKA CORPORATION USA

201 Polito Avenue · Lyndhurst, NJ 07071 · USA
 Phone: 800 933 SIKA · Fax: 201 933 6225 · www.sikausa.com